

# Oil Field Environmental Incident Summary

**Incident:** 20170620154959

**Date/Time of Notice:** 06/20/2017 15:49

**Responsible Party:** Henry Hill oil services

**Well Operator:** HENRY HILL OIL SERVICES, LLC

**Well Name:** ND STATE 1-16 SWD

**Field Name:** CATWALK

**Well File #:** 7504

**Date Incident:** 6/20/2017

**Time Incident:** 00:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 154

**Rng:** 100

**Sec:** 16

**Qtr:** SE SE

**Location Description:** 13215 hwhy 1804 Williston ND

**Submitted By:** Matt Azure

**Received By:**

**Contact Person:** Matt Azure  
120 26TH STREET EAST  
SUITE 200  
WILLISTON, ND 58801

**General Land Use:** Well/Facility Site

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine	4	Barrels	4	Barrels		
-------	---	---------	---	---------	--	--

Other

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

no risk

**Areal Extent:**

**Potential Environmental Impacts:**

no impact cleaned up immediately

***Action Taken or Planned:***

Getty parts replaced soil removed and placed in on site containment. tech will ck for corrosion and replace parts as needed.

***Wastes Disposal Location:*** soil was placed in on site containment and will be taken to waste landfill.

***Agencies Involved:***

***Updates***

---

***Date:*** 6/20/2017    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Stockdill, Scott

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

According to the incident summary this spill remained on location. NDIC retains oversight.